FieldShield®

Fiber Accessories



Furcation Kits -

Description

Available in 1, 2, 6 and 12-fiber kits, the FieldShield Furcation Kit provides all the components to upjacket and terminate 250 µm FieldShield Pushable Fiber using a 900 µm Splice-On Connectors.



Pre-Configured Part Numbers

Part Number	Description
FS-900UM-01-03F	FieldShield Furcation Kit for 3 mm jacketing, 1-fiber 900 µm, yellow tubing, 3 feet (914.40 mm)
FS-900UM-02-02F	FieldShield Furcation Kit for 3 mm jacketing, 2-fiber 900 µm, colored tubing, 2 feet (609.60 mm)
FS-900UM-06-02F	FieldShield Furcation Kit for 3 mm jacketing, 6-fiber 900 μm, colored tubing, 2 feet (609.60 mm)
FS-900UM-12-02F	FieldShield Furcation Kit for 3 mm jacketing, 12-fiber 900 µm, colored tubing, 2 feet (609.60 mm)
FS-900UM-24-02F	FieldShield Furcation Kit for 4 mm tube, 12-fiber 900 µm, colored tubing, 36 inches (914.40 mm)

Fiber End Face Cleaning Kits

Description

The Fiber End Face Cleaning Kit is the ideal solution to clean fiber end faces effectively every time.



Pre-Configured Part Numbers

Part Number	Description
Cleankit-SC-01	Ferrule and V groove swabs, SFF flat swab, 2.5 mm foam swabs, portable platform, fiber wash MX cleaner pen
Cleankit-LC-01	Ferrule and V groove swabs, SFF flat swab, 1.25 mm ferrule swab portable platform, fiber wash MX cleaner pen
Clean MPO-01	MPO chamois swabs, 25 per tube

www.SeeClearfield.com 1-800-422-2537